ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0170, W0223, W0027, W0174, W0176, W0217, W0215, W	NA	Ram Mandir ashwath Katte
Segment No.	**Total Length (m)**	
8/C-W0170/S115547	165.28	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	40.26	77.574008	13.058929	77.573917	13.058576	Main Road	Cross Road
2	73.88	77.574035	13.059127	77.574480	13.058840	Cross Road	Dead End
3	51.14	77.574649	13.059237	77.575105	13.059120	Cross Road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package No. 03 Package consists of 21 works	109000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1Providing and laying CC Road.	008-18-000048
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/148/2018-19	22/10/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/08/2020	11/08/2023	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
C.G.Chandrappa		0.00
Phone No.	**E-Mail ID**	
9448279709		

Zone: YELAHANKA Ward No: 8 Ward Name: Kodigehalli Street ID: W0170, W0223, W0027, W0174,

Assistant Executive Engineer
Kodigehalli Sub Division
BBMP

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Praveen A.R
Date of Inspection	**Remarks**	
31/08/2020		

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	23/11/2020	28/11/2020	As proposed
SE	Vijay Kumar Haridas	23/11/2020	28/11/2020	Forwarded
EE	MOhan Das H T	20/10/2020	30/09/2020	Approved
AEE	H.Ranganath	31/08/2020	30/09/2020	Verified
AE	Praveen A R	31/08/2020	30/09/2020	Mobile Verification Done
AE	Praveen A.R	31/08/2020	30/09/2020	Forwarded

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0170, W0223, W0027, W0174,

Assistant Executive Engineer
Kodigehalli

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli

Stroet ID	Stroet Name	Significant Landmark
W0255, W0204, W0271, W0214, W0216, W0228, W0253	Mahadevapura Village Rd, NA, Ambedkar Nagar Slum	Kodigehalli Village

Segment No.	Total Length (m)
8/C-W0255/S115030	103.99

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	13.68	77.575953	13.058796	77.576079	13.058793	Cross roads	Main road
2	90.31	77.575899	13.059151	77.576105	13.058581	Cross roads	Main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package No. 03 Package consists of 21 works	109000000	2018-19

Year	Type of Work	Other Work Type
2018 - 2019	Road	

Tender	Work Details	Job No. / Work Code
Tender	1.Providing and laying CC Road.	008-18-000048

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/148/2018-19	22/10/2018	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
12/08/2020	11/08/2023	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
C.G.Chandrappa		0.00

Phone No.	E-Mail ID
9448279709	

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Praveen A R
Date of Inspection	**Remarks**	
31/08/2020		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	23/11/2020	28/11/2020	As proposed
SE	Vijay Kumar Haridas	23/11/2020	28/11/2020	Forwarded
EE	MOhan Das H T	20/10/2020	30/09/2020	Approved
AEE	H.Ranganath	31/08/2020	30/09/2020	Verified
AE	Praveen A R	31/08/2020	30/09/2020	Mobile Verification Done
AE	Praveen A.R	31/08/2020	30/09/2020	Forwarded

Assistant Executive Engineer
Kodigehalli Sub Division
BBMP, Bangalore

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0255, W0204, W0271, W0214,

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0293, W0295, W0256, W0275	Maheshwari Nagar Opp Police Station Rd, NA, Ambedkar Nagar Slum	Megha Arts (Sapthagiri Hall)
Segment No.	**Total Length (m)**	
8/C-W0293/S114535	163.37	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	82.48	77.576178	13.057011	77.575985	13.056290	Main Road	Dead End
2	80.89	77.575985	13.057063	77.575770	13.056363	Main Road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package No. 03 Package consists of 21 works	109000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Desilting of drains.2.Providing and laying asphalt road.	008-18-000048
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/148/2018-19	22/10/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/08/2020	11/08/2023	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
C.G.Chandrappa		0.00
Phone No.	**E-Mail ID**	
9448279709		

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Praveen A R
Date of Inspection	**Remarks**	
31/08/2020		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	23/11/2020	28/11/2020	As proposed
SE	Vijay Kumar Haridas	23/11/2020	28/11/2020	Forwarded
EE	MOhan Das H T	20/10/2020	30/09/2020	Approved
AEE	H.Ranganath	31/08/2020	30/09/2020	Verified
AE	Praveen A R	31/08/2020	30/09/2020	Mobile Verification Done
AE	Praveen A.R	31/08/2020	30/09/2020	Forwarded

Assistant Executive Engineer
Kodigehalli Sub Division
BBMP, Bangalore

Zone: YELAHANKA Ward No: 8 Ward Name: Kodigehalli Street ID: W0293, W0295, W0256, W0275

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0627, W0629, W0618, W0604, W0616, W0623, W0615, W	NA, 1st Crs, 1st Main Rd, 8th Crs	Balaji Layout
Segment No.	**Total Length (m)**	
8/C-W0627/S112449	224.79	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	29.44	77.572971	13.049597	77.572910	13.049856	Cross raod	Dead End
2	25.23	77.573254	13.049672	77.573199	13.049894	Cross raod	Dead End
3	20.30	77.573537	13.049726	77.573492	13.049905	Cross raod	Dead End
4	15.13	77.573825	13.049786	77.573803	13.049921	Cross raod	Dead End
5	50.29	77.573903	13.047836	77.573931	13.048289	Cross raod	Dead End
6	84.40	77.573598	13.047522	77.573642	13.048284	Ring Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package No. 03 Package consists of 21 works	109000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Desilting of drains.2.Providing and laying asphalt.	008-18-000048
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/148/2018-19	22/10/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/08/2020	11/08/2023	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
C.G.Chandrappa		0.00
Phone No.	**E-Mail ID**	

Scanned by CamScanner

9448279709

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Praveen A R
Date of Inspection	**Remarks**	
31/08/2020		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	23/11/2020	28/11/2020	As proposed
SE	Vijay Kumar Haridas	23/11/2020	28/11/2020	Forwarded
EE	MOhan Das H T	20/10/2020	30/09/2020	Approved
AEE	H.Ranganath	31/08/2020	30/09/2020	Verified
AE	Praveen A R	31/08/2020	30/09/2020	Mobile Verification Done
AE	Praveen A.R	31/08/2020	30/09/2020	Forwarded

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0627, W0629, W0618, W0604,

Assistant Executive Engineer
Kodigehalli Sub Division
BBMP, Bangalore

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0587, W0602	2nd Crs, NA	Bhadrappa Layout
Segment No.	**Total Length (m)**	
8/S-W0587/S113043	43.46	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	13.36	77.572461	13.048438	77.572550	13.048522	10th A Cross	Dead End
2	30.10	77.571948	13.048840	77.572145	13.049032	10th C Cross	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package No. 03 Package consists of 21 works	109000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Providing and laying CC Road.	008-18-000048
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/148/2018-19	22/10/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/08/2020	11/08/2023	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
C.G.Chandrappa		0.00
Phone No.	**E-Mail ID**	
9448279709		

Scanned by CamScanner

Field Inspection Details

Number of Troos	Any Other Information	Name
0		Praveen A R
Date of Inspection	**Remarks**	
31/08/2020		

Catogory	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	23/11/2020	28/11/2020	As proposed
SE	Vijay Kumar Haridas	23/11/2020	28/11/2020	Forwarded
EE	MOhan Das H T	20/10/2020	30/09/2020	Approved
AEE	H.Ranganath	31/08/2020	30/09/2020	Verified
AE	Praveen A R	31/08/2020	30/09/2020	Mobile Verification Done
AE	Praveen A.R	31/08/2020	30/09/2020	Forwarded

Zone: YELAHANKA Ward No: 8 Ward Name: Kodigehalli Street ID: W0587, W0602

Date: 23/11/2020 Time: 16:39:42 RH 20201123163942

Assistant Executive Engineer
Kodigehalli

Scanned by CamScanner